

**Board Report**

File #: 2015-1687, **File Type:** Informational Report**Agenda Number:**

**SYSTEM SAFETY, SECURITY AND OPERATIONS COMMITTEE
FEBRUARY 18, 2016****SUBJECT: METRO PUBLIC ART ANNUAL REPORT****ACTION: RECEIVE AND FILE****RECOMMENDATION**

RECEIVE AND FILE **first annual report on the state of Metro's public artworks** in response to the Board Motion, Item 44 from the October 2015 System Safety, Security and Operations Committee.

ISSUE

At the October 2015 meeting, the Metro Board directed staff in Board Motion Item 44 (Attachment A) to provide an annual report on the state of Metro's public artworks starting in February 2016. Additionally, staff was directed to: beginning with the FY17 budget, dedicate a reasonable amount of funds towards maintenance and/or restoration of Metro's public artworks, include conservation and/or restoration of existing Metro public artworks in all future line, station, and facility refurbishment projects, budget additional funds as needed for maintenance of new Metro public artworks, such as artwork on the Expo Line Phase 2 and Gold Line Foothill extensions, create a regular maintenance plan for each Metro artwork, develop an action plan to restore artworks that are not functioning as intended, including consideration of using remaining Blue Line Upgrades Project funding for the restoration of artwork altered by that Project. Attachment A contains the October Board directive. This report provides the first annual report and responds to the directed items.

DISCUSSION

In October 2015, staff provided an initial inventory and assessment of all artworks in the Metro system, noting those which were known to not be functioning as intended at that time. In November 2015, staff provided a memo to the Board updating the assessment and providing an initial corrective action plan. This will be an evolving effort as artworks are added to the inventory and action plans are implemented. Some artworks are now approaching their 25th year and, like other assets in the Metro transit system, are subjected to the wear and tear of time and use, the marine environment and the ultraviolet (UV) sun quotient. Deferred art conservation is becoming increasingly visible and impacting the lifespan of several artworks.

Over the past 14 years, one Metro Art staff person has been responsible for managing the condition

of artworks in the system. During this time, the artworks have aged and more than doubled and the time allocated to monitoring each station's artwork has correspondingly been significantly reduced. The staff person serves as a technical subject expert and manages specialized art refurbishment and conservation contracts as resources allow. Operations staff regularly removes dust, dirt and debris from a number of artworks as part of their station cleaning. However, due to the unique nature and location, the majority of artworks require special attention and care.

Annual Report

Attachment B contains the updated list of artworks in the Metro system as of January 2016 and outlines an action plan for each. Additional artworks will be coming on line later this year with the opening of the Gold Line Foothill and Expo 2 Extensions. This report will be expanded, updated and presented to the Board on an annual basis and includes the station, artist, title, year installed, as well as the current status of the work and proposed action plan.

FY17 Budget

Metro Art is currently resourced with the abovementioned dedicated FTE for art asset management including a limited number of inspections and minor art conservation and repair projects. To address the aging system, staff is evaluating the resources necessary to provide for a more substantive range of conservation and repairs to ensure that artworks do not fall into a state of deterioration or disrepair. Based on this evaluation, staff will submit a reasonable request for resources in the proposed FY17 and future fiscal year budgets to enable as many annual inspections of each of the artworks in the system as resourced, professional conservator reports identifying recommended actions, where necessary, and implementation of a select number of cleaning, repairs and specialized artwork conservation projects each year as budget allows. Attachment B is divided into two parts, Attachment B-1 includes those projects that will be part of the FY17 budget, assuming existing resources continue; and Attachment B-2 shows additional projects that could be addressed should additional resources be approved in the FY17 budget and beyond.

Future Facility Refurbishment or Modification Projects

Recent line, station and facility refurbishment or modification projects have resulted in the unanticipated relocation, alteration or even removal of some artworks. In order to ensure appropriate conservation and/or restoration of existing artworks, Metro staff will work together during early project development and scoping to ensure that the integrity of artworks is addressed.

Funding for Gold Line Foothill and Expo 2 Extensions

With the forthcoming opening of the Gold Line Foothill and Expo 2 Extensions, an additional 14 artworks will be added to the system over the next few months. With the acceptance of these lines, the new artworks will be added to the database over the course of FY17 and resources to ensure the works remain in a state of good repair will be requested in FY18.

Regular Conservation Plans for Each Artwork

Pending allocation of resources in the FY17 budget, regular conservation plans will be developed for artwork as resources permit. This will be a multi-year effort, with the first year including inspection of the work and the development of an action plan, with implementation of the plan budgeted in succeeding years. The completion of the action plan will be contingent upon sufficient annual resources being allocated.

Action Plan to Restore Artworks Not Currently Functioning as Intended

As reported in the November 10, 2015 Board memo, of the 19 artworks identified as not functioning as intended, one has been repaired, three are being refurbished as part of Union Station improvement projects, and artworks that were removed or altered by the Blue Line Improvement Project are in the process of being replaced or renovated. The one remaining non-functioning artwork on the Blue Line, *Unity*, by artist Thomas Eatherton is an inaugural artwork installed in the Metro Rail system 25 years ago, has been submitted for consideration as a new small Capital Project in the FY17 budget. Action plans to restore the remaining nine artworks will be developed in FY17 pending approval of resources.

NEXT STEPS

Staff will continue to work cross-departmentally and apply lessons learned to new corridor construction and refurbishments in order to safeguard the aesthetic integrity and longevity of the system's artworks as cultural and community assets. Durable materials and finishes, as well as artwork locations are key aspects to ensure that artworks function as intended. Staff will manage the implementation of currently resourced conservation refurbishments as outlined in the November 10, 2015 Board memo. As directed by the Board, staff will request a reasonable amount of resources in the FY17 budget and future year budgets to assess, conserve and/or restore artworks in the system to ensure they are kept in a state of good repair.

ATTACHMENTS

Attachment A - October 2015 Board Directive

Attachment B - Metro Public Art Collection Assessment Report


Prepared by: Maya Emsden, Deputy Executive Officer (213) 922-2720

Renee Berlin, Managing Executive Officer (213) 922-3035

Diane Corral-Lopez, Deputy Executive Officer, Operations (213) 922-7676

Reviewed by: James T. Gallagher, Chief Operations Officer, (213) 922-4424

Calvin E. Hollis, Interim Chief Planning Officer, (213) 922-7319



Phillip A. Washington
Chief Executive Officer

MOTION BY:

**DIRECTOR JACQUELYN DUPONT-WALKER, SUPERVISOR SHEILA KUEHL
AND DIRECTOR JOHN FASANA**

MTA Operations Committee

October 15, 2015

Item 44: MTA Public Art

MTA's public art is an important part of the customer experience.

Public art that is maintained in a state of good repair reinforces the fact that MTA is caring for its system and cares about the experience of its customers.

Conversely, public art that is not in a state of good repair reinforces a perception that MTA is not caring for its system and does not have regard for the experience of its customers.

The first public art in the MTA system was installed in 1991, nearly 25 years ago. Today, MTA has a total of 152 public artworks across all of its rail lines, Union Station, the Gateway Center complex, Division 9, Division 13, and other locations.

Currently, 19 of MTA's 152 public artworks are not functioning as intended due to various factors, including vandalism, electrical failure, and capital projects.

I, THEREFORE, MOVE that the Board instruct the CEO to:

- A. Provide an annual report on the state of MTA's public artworks.
- B. Beginning with the Fiscal Year 2017 budget, dedicate a reasonable amount of funds towards maintenance and/or restoration of MTA public artworks.
- C. Include conservation and/or restoration of existing MTA public artworks in all future line, station, and facility refurbishment projects.
- D. Budget additional funds as needed for maintenance of new MTA public artworks, such as artwork on the Expo Line Phase 2 and Gold Line Foothill Extension.
- E. Create a regular maintenance plan for each MTA public artwork.

CONTINUED

F. Develop an action plan to restore MTA public artworks that are not functioning as intended, including consideration of using remaining Blue Line Upgrades Project funding for the restoration of artwork altered by the Blue Line Upgrades Project.

G. Report back on all the above during the February 2016 MTA Board cycle.

###

Metro Public Art Collection Assessment Report
FY17 Work Program Assuming Current Resources

Metro Blue Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
1 Willowbrook / Rosa Parks	Joe Sam	<i>Hide-n-Seek</i> Painted steel sculpture	1993	Pigeon abatement issues as well as recurring delamination of paint at artwork resulting in corrosion.	FY17 Work Program plans will include inspection of artwork elements and the development of a condition and corrective action report, assuming existing resources continue.
2 Grand / LATTC	Mark Lere	<i>Who, What, Where?</i> Etched and paint filled granite tile paving; etched and paint filled concrete	1994	Artwork completely removed during Metro Blue Line Refurbishment Project.	FY17 Work Program plans will include contracting with Artist to replace artwork, using FY16 capital project funds approved on 01/11/16. Scheduled completion FY18.
3 103rd Street / Watts Towers	Roberto Salas	<i>Blue Line Totems in Red</i> Painted steel columns; ceramic tile	1994	Artwork partially removed during Metro Blue Line Refurbishment Project.	FY17 Work Program plans will include contracting with Artist to refurbish and renovate artwork, using FY16 capital project funds approved on 01/11/16. Scheduled completion FY18.
4 5th Street	Jim Isermann	<i>Failed Ideals</i> Stain glass medallions	1995	Artwork partially removed during Metro Blue Line Refurbishment Project.	FY17 Work Program plans will include contracting with fabricator/installer to renovate and replace artwork, using FY16 capital project funds approved on 01/11/16. Scheduled completion FY18.
5 Artesia	Lynn Aldrich	<i>Blue Line Oasis</i> Stainless steel and ceramic sculpture; glass mosaic tile, painted steel wishing well; glass mosaic panels	1996	Minor repairs appear necessary at glass mosaic artwork.	FY17 Work Program plans will include artwork inspection and development of condition and corrective action report and completion of minor repairs, assuming existing resources continue.
6 Washington	Elliot Pinkney	<i>Running for the Blue Line</i> Painted steel panels; painted columns	1997	Artwork paint requires correction due to Metro Blue Line Refurbishment Project.	FY17 Work Program plans will include inspection of artwork elements and the development of a condition and corrective action report, and completion of paint correction, assuming existing resources continue.
7 Willowbrook / Rosa Parks	Judy Baca	<i>Metate Bench</i> GFRC benches with ceramic tile	2008	Artwork inspection required.	FY17 Work Program plans will include inspection of artwork elements, assuming existing resources continue.

Metro Green Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
8 Redondo Beach	Carl Cheng	<i>The Museum of Space Information</i> Painted steel satellite towers and satellite; painted steel TV Monitor cabinets and monitors; painted steel, glass and mixed media windscreens, concrete, glass, stone and stainless steel benches; concrete and resin planet formations; glass and mixed media illuminated diorama; glass, stone and steel inlays; porcelain enamel mural	1995	Structural elements supporting artwork appear in poor condition, damaged, artwork satellite feed not working.	FY17 Work Program plans will include Metro Engineering review and report on artwork supporting structures, an inspection by an arts conservator and the development of a condition and corrective action report, assuming existing resources continue. Pending results of these reports funds will be requested in future years to address action items, if any.
9 Douglas	Renee Petropoulos	<i>Untitled</i> Painted steel medallions; painted steel and galvanized steel tower, painted steel fencing; painted steel and concrete stools and benches; bronze inlays; bronze and painted steel telescopes; anodized aluminum panels; stamped text in concrete; porcelain enamels murals; terrazzo and bronze mural paving; ceramic tiles; glass with laminated imagery	1995	Sculpted artwork medallions appear damaged.	FY17 Work Program plans will include inspection of artwork elements by arts conservator and the development of a condition and corrective action report, assuming existing resources continue. Pending results of this report funds will be requested in future years to address action items, if any.
10 El Segundo	Daniel J. Martinez	<i>For Your Intellectual Entertainment</i> Painted steel and galvanized steel structures, painted steel fencing; painted steel and concrete stools and benches; bronze inlays; bronze and painted steel telescopes; clocks; stamped text in concrete; porcelain enamels murals; terrazzo and bronze mural paving	1995	Artwork electronic element not working.	FY17 Work Program plans will include inspection of artwork elements by arts conservator and the development of a condition and corrective action report, assuming existing resources continue. Pending results of this report funds will be requested in future years to address action items, if any.
11 Hawthorne / Lennox	Mineko Grimmer	<i>Companions</i> Patinated bronze sculptures; black granite benches	1995	Artwork sculpture damaged/etched.	FY17 Work Program plans will include completion of repair, reinstallation and documentation of artwork, assuming existing resources continue.
12 Long Beach Blvd	Sally Weber	<i>Celestial Chance</i> Terra cotta tile mural paving; pigmented concrete and steel paving, painted steel sculptures; perforated steel and acrylic sculpture	1995	Artwork sculpture appears to require paint touch up and minor repairs to paving.	FY17 Work Program plans will include inspection of artwork elements and the development of a condition and corrective action report, assuming existing resources continue.

Metro Red Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
13 Civic Center / Grand Park	Johnathan Borofsky	<i>I Dreamed I Could Fly</i> Hand painted fiberglass sculpture; audio playback system; spotlights	1993	Artwork requires new audio component.	FY17 Work Program plans will include artwork inspection and development of condition and corrective action report and minor repairs, assuming existing resources continue.
14 Vermont / Beverly	George Stone	<i>Untitled</i> Glass fiber reinforced concrete sculptural rock formations	1999	Artwork inspection required.	FY17 Work Program plans will include inspection of artwork elements, assuming existing resources continue.
15 Hollywood/Highland	Sheila Klein	<i>Underground Girl</i> Painted aluminum fixtures, electrical; aluminum and stainless sculpture	2000	Electronic artwork not working and inaccessible. General (non-art) lighting in area requires resolution.	FY17 Work Program plans will include inspection of artwork elements and recommendations regarding artwork accessibility and lighting conditions, assuming existing resources continue.
16 North Hollywood	Anne Marie Karlsen	<i>Kaleidoscope Dreams</i> Ceramic tile	2000	One artwork mural currently being relocated as a result of underpassage project.	FY17 Work Program plans will include artwork mural relocation and documentation, assuming existing resources continue.
17 Vermont / Beverly	Rotating Artist	<i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Artwork inspection required.	FY17 Work Program plans will include artwork inspection and replacements/rotation, assuming existing resources continue.
18 Hollywood / Highland	Rotating Artist	<i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Artwork inspection required.	FY17 Work Program plans will include artwork inspection and replacements/rotation, assuming existing resources continue.
19 Universal City / Studio City	Rotating Artist	<i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Artwork inspection required.	FY17 Work Program plans will include artwork inspection and replacements/rotation, assuming existing resources continue.
20 7th Street / Metro Center	K. Kobayashi, N. Korten & M. Perlas	<i>Plantings</i> Pigmented concrete benches; cast aluminum, painted steel, gobos and electrical components	2002	Artwork benches were relocated due to Expo Line impacts. Electronics and artwork lighting needs replacement.	FY17 Work Program plans will include replacement of artwork lighting components, assuming existing resources continue.

Metro Red / Purple Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
21 7th Street / Metro Center	Rotating Artist	<i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Artwork inspection required.	FY17 Work Program plans will include artwork inspection and replacements/rotation, assuming existing resources continue.

Metro Purple Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
22 Wilshire / Normandie	Rotating Artist	<i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Artwork inspection required.	FY17 Work Program plans will include artwork inspection and replacements/rotation, assuming existing resources continue.

Metro Gold Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
23 Highland Park	Jud Fine	<i>Stone Tree Inverted Post (Bound Water Light)</i> Pigmented illuminated acrylic domes; concrete benches; pigmented glass fiber reinforced concrete and bronze sculpture	2003	GFRC artwork requires sealant.	FY17 Work Program plans will include artwork treatment and sealant, assuming existing resources continue.
24 Lake	Pat Ward Williams	<i>Everyday People</i> Laminated imagery within glass panels	2003	Artwork panel damaged.	FY17 Work Program plans will include completion of repair, reinstallation and documentation of artwork, assuming existing resources continue.
25 Sierra Madre Villa	Beth Thielen	<i>Images of Commonality / Nature and Movement</i> Concrete reliefs; glass mosaic and concrete mural paving; painted steel, acrylic and electrical light box	2003	Artwork electronics no longer functioning.	FY17 Work Program plans will include inspection of artwork elements and the development of a condition and corrective action report, and minor repairs, assuming existing resources continue.

Metro Silver Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
26 Harbor Gateway Transit Center	Alison Saar	<i>Paraje</i> Stainless steel sculpture	2012	Artwork inspection required.	FY17 Work Program plans will include inspection of artwork elements, assuming existing resources continue.

Metro Facilities					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
27 Union Station: Gateway Transit Center	May Sun & Richard Wyatt	<i>City of Dreams, River of History</i> Aquarium, glass, plants, fish, water, lighting and electrical components	1995	Artwork requires refurbishment of aquatic life system.	FY17 Work Program plans will include working with Morlin Property Management to refurbish artwork, assuming existing resources continue.

Metro Facilities					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
28 Union Station: Gateway Transit Center	Roberto Gil de Montes	<i>Paseo Cesar Chavez</i> Ceramic tile benches; ceramic tile fountain	1995	Artwork requires partial refurbishment of pump system, and repair of artwork.	FY17 Work Program plans will include inspection of artwork elements and minor repairs, assuming existing resources continue.
29 Union Station: Gateway Transit Center	P. Shire, E. Flores, R. Gil de Montes	<i>Paseo Cesar Chavez</i> Ceramic tile bench	1995	Artwork requires partial refurbishment of pump system, and repair of artwork.	FY17 Work Program plans will include inspection of artwork elements and minor repairs, assuming existing resources continue.
30 Metro Customer Service Center (former)	Jim Isermann	<i>Untitled (Tilfords)</i> Powder coated aluminum panels	2006	Artwork removed as part of Purple Line Extension. Artwork to be relocated /re-purposed.	FY17 Work Program plans will include researching suitable sites to appropriately relocate artwork, assuming existing resources continue.
31 Division 9 Facility	Raul de la Sota	<i>Forward to the Past</i> Painted honey comb aluminum mural	2007	Artwork inspection required.	FY17 Work Program plans will include inspection of artwork elements, assuming existing resources continue.
32 Union Station Passageway	Rotating Artist	<i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Artwork inspection required.	FY17 Work Program plans will include artwork inspection and replacements/rotation, assuming existing resources continue.

Additional FY17 Proposed Work Program with Additional Resources

Metro Blue Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
33 Blue Line Tunnel	Thomas Eatherton	<i>Unity</i> LED light sculpture installations	1991	Electronic artwork requires replacement and renovation.	FY17 Capital Budget has been requested to replace fiber-optic artwork with new, more efficient LED panels. This request has been deferred due to other higher priority needs agencywide.
34 Wardlow	Jacqueline Dreager	<i>Great Gathering Place</i> Fiberglass, bronze and steel sculptures; Concrete and steel stools; Glass medallion with imagery	1992	Fiberglass artwork sculptural element deteriorating.	Request additional FY17 resources to do artwork inspection.
35 7th Street / Metro Center	Joyce Kozloff	<i>The Movies: Fantasies and Spectacles</i> Ceramic tile murals	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
36 7th Street / Metro Center	Roberto Gil de Montes	<i>Heaven to Earth</i> Ceramic tile murals	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
37 Pico	Robin Brailsford	<i>Time and Presence</i> Painted steel canopy panels	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
38 San Pedro Street	Sandra Rowe	<i>Hope, Dream, Path, Focus, Belief</i> Patinated, etched, pigmented waxed bronze panels; stainless steel kinetic sculptures	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
39 Vernon	Horace Washington	<i>A Tribute to Industry</i> Bronze and powder coated steel stools; galvanized steel benches; stainless steel and painted steel sculpture; ceramic tile	1994	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
40 Pacific Coast Highway	Joe Lewis	<i>Twelve Principals</i> Ceramic tile medallions	1994	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
41 Anaheim Street	Terry Braunstein	<i>Local Odysseys</i> Porcelain enamel medallions	1994	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
42 Slauson	East Los Streetscapers	<i>South Central Suite</i> Porcelain enamel panels; ceramic tile and pigmented concrete and ceramic tile murals	1995	Two artwork panels missing.	Request additional FY17 resources to do artwork inspection and condition report.
43 Compton	Eva Cockcroft	<i>Past, Present and Future</i> Ceramic tile panels; ceramic tile columns	1995	Artwork tile appears damaged.	Request additional FY17 resources to do artwork inspection.

Metro Blue Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
44 1st Street	Paul Tzanetopoulos	<i>Breezy and Delightful</i> Porcelain enamel kinetic medallions	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
45 Downtown Long Beach	Patrick Mohr	<i>Angel Train</i> Anodized aluminum sculptures	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
46 Pacific Ave	June Edmonds	<i>We Know Who We Are</i> Glass mosaic medallions	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
47 Del Amo	Colin Gray	<i>Del Amo Wheel</i> Glass fiber reinforced concrete sculpture	1999	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
48 Willowbrook / Rosa Parks	Michael Massenburg	<i>Pathways To Freedom</i> Glass mosaic, ceramic tile and concrete benches	2002	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
49 Firestone	Ricardo Mendoza	<i>The Will to Progress</i> Ceramic tile mural panels	2004	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
50 Florence	Ricardo Duffy	<i>A Florence Moment</i> Ceramic tile murals	2005	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
51 Willow	Merge Conceptual Design	<i>Out of Sight</i> Glass canopy with laminated imagery, GFRC bench	2006	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Green Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
52 Mariposa	Charles Dickson	<i>Divine Order: the Manifestation of the Soaring Spirit</i> Painted, pigmented concrete benches; ceramic tiles; glass and laminated imagery; terrazzo and bronze mural paving; ceramic tile cutouts; concrete relief mural; ceramic tile columns	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
53 Aviation / LAX	Richard Turner	<i>Untitled</i> Glass and laminated imagery; terrazzo and bronze mural paving; pigmented concrete and steel chairs, tables and benches; painted steel panels	1995	Artwork sculptures require paint touch up, minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection.

Metro Green Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
54 Crenshaw	Buzz Spector	<i>Crenshaw Stories</i> Ceramic tile murals; concrete benches; terra cotta tile paving; concrete impressions	1995	Minor damage at artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
55 Vermont / Athens	Kim Yasuda	<i>Real Green</i> Ceramic tile murals; terrazzo and bronze mural paving; painted steel and wood benches; wood, painted aluminum and steel sculptural buckets	1995	Minor cracking at artwork terrazzo paving.	Request additional FY17 resources to do artwork inspection and condition report.
56 Harbor Fwy	Steve Appleton	<i>Locus: City Imprints</i> Granite benches; pigmented concrete and steel benches; glass fiber reinforced concrete sculptures; pigmented concrete mural paving	1995	Artwork sculpture vandalized.	Request additional FY17 resources to do artwork inspection and condition report.
57 Avalon	Willie Middlebrook	<i>Portrait of My People #619</i> Porcelain enamel murals	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
58 Avalon	John Outterbridge	<i>Pyramid</i> Concrete and ceramic tile sculptures; pigmented concrete mural paving	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
59 Avalon	Stanley C. Wilson	<i>Bridge of Culture</i> Pigmented and ceramic tile benches; ceramic tile mural paving, painted steel panels	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
60 Lakewood Blvd	Erika Rothenberg	<i>Wall of (Un)Fame</i> Pigmented concrete panels; pigmented concrete benches; pigmented concrete receptacles; painted steel grills; bronze plaque	1995	Artwork requires cleaning. Inspection required.	Request additional FY17 resources to do artwork inspection.
61 Norwalk	Meg Cranston	<i>Suka: Place of Bees</i> Ceramic tile; bronze tile; painted stainless steel sculptures; laminated imagery; painted steel and fiberglass sculptures	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Red Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
62 Union Station	Christopher Sproat	<i>Union Chairs</i> Granite benches	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Red Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
63 Union Station	Terry Schoonhoven	<i>Traveler</i> Ceramic tile mural	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
64 Union Station	Cynthia Carlson	<i>LA: City of Angels</i> Hand painted mural with reliefs	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
65 Pershing Square	Stephen Antonakos	<i>Neons for Pershing Square</i> Neon sculptures	1993	Artwork neon lighting transformers not working.	New neon transformers installed in FY16. Request additional FY17 resources to do artwork inspection.
66 Westlake / MacArthur Park	Therman Statom	<i>Into the Light</i> Glass skylight; acrylic, aluminum, stainless steel and painted steel sculptures; ceramic tile	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
67 Vermont / Santa Monica	Robert Millar	<i>Untitled</i> Text painted on walls throughout; aluminum and polycarbonate panels; colored lighting	1999	Artwork requires bulb replacement.	Request additional FY17 resources to do artwork inspection and condition report.
68 Vermont / Sunset	Michael Davis	<i>Ecliptic/Illume</i> Copper, porcelain enamel, stainless steel sculptures; lighting; granite and aluminum paving	1999	Artwork requires bulb replacement.	Request additional FY17 resources to do artwork inspection and condition report.
69 Hollywood / Western	May Sun	<i>Untitled</i> Painted aluminum and polycarbonate sculptures; lighting; terrazzo and copper paving murals; etched granite; patinated bronze; ceramic tile throughout	1999	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
70 Hollywood/Vine	Gilbert "Magu" Lujan	<i>Hooray for Hollywood</i> Painted fiberglass and pigmented concrete benches, hand painted ceramic tiles	1999	Platform sculptural elements damaged and removed.	Request additional FY17 resources for artwork inspection and condition report. Funds will be requested in future years to procure a Conservator to develop corrective action plan.
71 Universal City/Studio City	Margaret Garcia	<i>Tree of Califas</i> Carved ceramic tile; stainless steel, painted steel and granite benches; laminated imagery	2000	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
72 Vermont / Santa Monica	George Legrady	<i>Kinetic Flow</i> Porcelain enamel mural	2006	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
73 Westlake / MacArthur Park	Sonia Romero	<i>MacArthur Park, Urban Oasis</i> Hand carved porcelain mosaic panels	2010	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Red Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
74 Vermont / Beverly	Tyree Guyton	<i>People in Motion</i> Glass mosaic mural	2010	Artwork inspection required.	Request additional FY17 resources to do artwork inspection and condition report.
75 Universal City / Studio City	Stephen Johnson	<i>Untitled</i> Glass mosaic mural	2010	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Red / Purple Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
76 Westlake / MacArthur Park	Francisco Letelier	<i>El Sol/La Luna</i> Ceramic tile murals	1993	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
77 Union Station	Bill Bell	<i>A Train</i> LED light sticks, audio and video components	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection and condition report.
78 Wilshire / Vermont	Peter Shire	<i>Los Angeles Seen</i> Painted steel and stainless steel sculptures	1996	Artwork kinetic motorized function not working.	Request additional FY17 resources to do artwork inspection and condition report.
79 Civic Center / Grand Park	Peter Requam	<i>Civic Center Benches</i> Granite benches	2004	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
80 Civic Center / Grand Park	Samm Kunce	<i>In the Living Rock</i> Glass mosaic and granite murals	2004	Minor etching at granite artwork (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.
81 Wilshire / Vermont	Bob Zoell	<i>No Title</i> Ceramic tile murals	2004	Minor etching at granite artwork (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.
82 Civic Center Station	Faith Ringgold	<i>People Portraits: in Creativity, Performing, Sports & Fashion</i> Glass mosaic panels	2010	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Purple Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
83 Wilshire/Normandie	Frank Romero	<i>Festival of Masks Parade</i> Painted aluminum mural	1996	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Purple Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
84 Wilshire / Western	Richard Wyatt	<i>People Coming People Going</i> Ceramic tile murals	1996	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
85 Wilshire / Western	Pae White	<i>The Beppins</i> Pigmented concrete stools; seeded lithocrete paving	2003	Minor damage to artwork seating sculptures (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.

Metro Gold Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
86 Chinatown	Chusien Chang	<i>The Wheels of Change</i> Painted aluminum benches; etched granite, glass and stainless steel compass; bronze bell; etched granite tile pavers	2003	Benches are etched (vandalized), require painting.	Request additional FY17 resources to do artwork inspection and condition report.
87 Lincoln / Cypress	Cheri Gualke	<i>Water Street: River of Dreams</i> Patinated copper, lexan and stainless steel panels; patinated bronze sculpture; stone boulders and seeded glass arroyo; concrete impressions	2003	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
88 Heritage Square	Roberto L. Delgado	<i>El Quetzalcoatl de Xochicalco and La Gente del Pueblo</i> Ceramic tile paving; carved volcanic stone sculpture with rebar attachments	2003	Artwork sculpture at planters is degrading.	Request additional FY17 resources to do artwork inspection and condition report.
89 Southwest Museum	Teddy Sandoval	<i>Highland Park Gateway</i> Glass fiber reinforced concrete and ceramic tile benches; glass fiber reinforced concrete, aluminum and glass mosaic sculptures; painted steel chairs; glass seeded arroyo paving	2003	Minor separation at GFRC artwork columns.	Request additional FY17 resources to do artwork inspection and condition report.
90 South Pasadena	Michael Stutz	<i>Astride-Aside</i> Patinated bronze, painted steel sculpture; stone pedestals	2003	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
91 Fillmore	Michael C. McMillen	<i>Geologica 42</i> Patinated bronze sculptures	2003	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
92 Del Mar	Ries Niemi	<i>Kinetic Energy</i> Stainless steel fencing	2003	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Gold Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
93 Memorial Park	John Valadez	<i>The First Artist in Southern California: A Short Story</i> Painted steel sculpture	2003	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
94 Allen	Michael Amescua	<i>Rider's Dream</i> Stainless steel sculpture; glazed terra cotta paving; painted steel and stainless steel panels	2003	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
95 Sierra Madre Villa	Tony Gleaton	<i>Untitled</i> Porcelain enamel panels	2003	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
96 Union Station	Roy Nicholson	<i>Solar Shift: San Bernardino and Santa Monica</i> Glass mosaic murals	2006	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
97 Atlantic	Adobe LA	<i>Blissful Interiors</i> Painted steel sculpture; GFRC pigmented benches; ceramic tile paving	2009	Artwork requires cleaning and abatement film replacement.	Request additional FY17 resources to do artwork inspection and condition report.
98 East LA Civic Center	Clement Hanami	<i>Through the Looking Glass or Traveling at the Speed of Light (Rail)</i> Painted steel sculpture; pigmented concrete paving	2009	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
99 Maravilla	Jose Lopez	<i>Maravilla Hearts of Tokens</i> Stainless steel sculptures; aluminum panels	2009	Artwork requires sealant.	Request additional FY17 resources to do artwork inspection and condition report.
100 Indiana	Paul Botello	<i>Syncretic Manifestations</i> Stainless steel panels	2009	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
101 Soto	Nobuho Nagasawa	<i>Landings</i> Aluminum panels of imagery and text; Glass curtain wall; Stainless steel, acrylic and LED sculpture	2009	Artwork inspection required.	Request additional FY17 resources to do artwork inspection and condition report.
102 Mariachi Plaza	Alejandro de la Loza	<i>El Nino Perdido</i> Cast bronze sculptures; granite panels	2009	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
103 Pico / Aliso	Rob Nielson	<i>About Place About Face</i> Cast iron sculptures	2009	Artwork requires sealant.	Request additional FY17 resources to do artwork inspection and condition report.
104 Little Tokyo / Arts District	Hirokazu Kosaka	<i>Buffer Zone</i> Granite benches	2009	Minor etching at artwork granite (vandalism).	Station, including artwork, to be fully demolished in 2019.

Metro Orange Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
105 Alignment	Jud Fine	<i>Seven Spots and a Path</i> Alignments landscaping	2005	Artwork inspection required.	Request additional FY17 resources to do artwork inspection and condition report.
106 North Hollywood	Caryl Davis	<i>Dramatic Local</i> Porcelain enamel steel panel; terrazzo mural paving	2005	Abatement film at artwork panel requires replacement, minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
107 Laurel Canyon	Phung Huynh	<i>Lucky California</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
108 Valley College	Laura London	<i>Former Location/Contemporary Portrait</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
109 Valley College, Van Nuys, Sepulveda, Balboa, Reseda	Renee Petropoulos	<i>14 Miles</i> Terrazzo benches	2005	Minor cracking / chipping at terrazzo artwork.	Request additional FY17 resources to do artwork inspection and condition report.
110 Woodman	Daniel Marlos	<i>Journey to California</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
111 Van Nuys	Roxene Rockwell	<i>VAN NUYS, The New Town</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
112 Sepulveda	Michele Martinez	<i>Todos Vuelven</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
113 Woodley	John Roloff	<i>Valley Scan</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at panels (vandalism), minor cracking at terrazzo paving.	Request additional FY17 resources to do artwork inspection and condition report.
114 Balboa	John O'Brien	<i>OverSite</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.

Metro Orange Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
115 Reseda	Jody Zellen	<i>Now and Then</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
116 Tampa	Sandow Birk	<i>Tarzan and Tarzana</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
117 Pierce College	Pat Warner	<i>What We See</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
118 De Soto	John Divola	<i>Images From Dogs Chasing My Car in the Desert</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism), minor cracking at terrazzo artwork paving.	Request additional FY17 resources to do artwork inspection and condition report.
119 Canoga	Roy Dowell	<i>Consturcted Histories</i> Porcelain enamel steel panels; terrazzo mural paving	2005	Minor etching at artwork panels (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.
120 Canoga	Ken Gonzales-Day	<i>Western Imaginary</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Minor etching at artwork panels (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.
121 Sherman Way	Margaret Lazzari	<i>Ovensmouth / Canoga Park</i> <i>Porcelain enamel steel panels; stone and glass mosaic mural paving</i>	2012	Minor etching at artwork panels (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.
122 Roscoe	Sam Erenberg	<i>Liquid Light: Flowing Into The Future</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Minor etching at artwork panels (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.
123 Nordhoff	Anne Marie Karlsen	<i>Strati</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Minor etching at artwork panels (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.
124 Chatsworth	Lisa Adams	<i>A Glimpse of Stoney Point</i> Porcelain enamel steel panels; stone and glass mosaic mural paving	2012	Minor etching at artwork panels (vandalism).	Request additional FY17 resources to do artwork inspection and condition report.

Metro Silver Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
125 Cal State LA	Merge Conceptual Design	<i>Overcoat - CSULA</i> Painted steel; painted concrete; Ceramic tile	2009	Artwork requires painting.	Request additional FY17 resources to do artwork inspection and condition report.
126 LAC + USC Medical Center	Merge Conceptual Design	<i>Untitled</i> Painted steel; painted concrete; Ceramic tile	2009	Artwork requires painting.	Request additional FY17 resources to do artwork inspection and condition report.
127 El Monte Transit Center	Donald Lipski	<i>Time Piece</i> Stainless steel sculpture; painted steel and electronic sculpture	2012	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
128 El Monte Transit Center	Eloy Torrez	<i>The Steps We Take</i> Powder coated sublimation murals	2014	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
129 El Monte Transit Center	Martin Durazo	<i>Vamos Juntos/Juntas</i> Powder coated sublimation murals	2014	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
130 El Monte Transit Center	Phung Huyn	<i>In The Meadow</i> Powder coated sublimation murals	2014	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
131 El Monte Transit Center	Vincent Ramos	<i>El Monte Legion Stadium</i> Powder coated sublimation murals	2014	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Expo Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
132 LATT / Ortho Institute	Christofer C. Dierdorff	<i>The Intimacy of Place</i> Porcelain enamel steel panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.
133 Jefferson / USC	Samuel Rodriguez	<i>Urban Dualities</i> Hand-glazed, hand-cut ceramic mosaic panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.
134 Expo Park / USC	Robbert Flick	<i>On Saturdays</i> Photographic porcelain tile panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.

Metro Expo Line					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
135 Expo / Vermont	Jessica Polzin McCoy	<i>Neighborhood Portrait: Reconstructed</i> Hand-glazed, hand-cut ceramic mosaic panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.
136 Expo / Western	Ronald J. Llanos	<i>Ephemeral Views: A Visual Essay</i> Hand-glazed, hand-cut ceramic mosaic panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.
137 Expo / Crenshaw	Willie Robert Middlebrook Jr.	<i>Wanderers</i> Glass mosaic panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.
138 Farmdale	Michael Massenburg	<i>All in a Day</i> Glass mosaic panels	2012	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
139 Expo / La Brea	Jose Lozano	<i>LA Metro Loteria</i> Commercial tile, ink sublimation panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.
140 La Cienega / Jefferson	Daniel Gonzales	<i>Engraved in Memory</i> Hand-glazed, hand-cut ceramic porcelain mosaic panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.
141 Culver City	Tom LaDuke	<i>Unknowable Origins</i> Glass mosaic panels	2012	Failed paint system on Expo 1 station structures may compromise artwork.	Request additional FY17 resources to do artwork inspection. Detailed analysis of station paint system failure impacts may be necessary in future years.

Metro Facilities					
Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
142 Union Station: Gateway Transit Center	James Doolin	<i>Los Angeles Circa 1870, 1910, 1950 and after 2000</i> Painted murals	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
143 Union Station: Gateway Transit Center	Margaret Nielsen	<i>LA Dialogs</i> Painted mural	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.

Metro Facilities						
	Station	Artist	Artwork Title / Components	Year Installed	Status	Action Plan
144	Union Station: Gateway Transit Center	Patrick Nagatani	<i>Epoch</i> Painted mural	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
145	Union Station: Gateway Transit Center	May Sun	<i>City of Dreams, River of History</i> Pigmented concrete, glass, steel and ceramic tile fountain; stone, patinated bronze paving; ceramic tile benches	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
146	Union Station: Gateway Transit Center	Richard Wyatt	<i>City of Dreams, River of History</i> Painted mural	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
147	Union Station: Gateway Transit Center	East Los Streetscapers	<i>La Sombra del Arroyo</i> Painted bronze sculpture; ceramic tile; stone tile	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
148	Union Station: Gateway Transit Center	Kim Yausda & Noel Korten	<i>ReUnion</i> <i>Stainless steel, glass and copper bus shelters</i>	1995	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.
149	Union Station: Gateway Transit Center	Michael Amescua	<i>Guardians of the Track</i> Painted steel panels; anodized aluminum panels	1995	Artwork sculptures require cleaning and paint touch ups.	Request additional FY17 resources to do artwork inspection and condition report.
150	Union Station: Gateway Transit Center	Peter Shire	<i>Paseo Cesar Chavez</i> Ceramic tile benches	1995	Artwork benches are etched (vandalized).	Request additional FY17 resources to do artwork inspection and condition report.
151	Union Station: Gateway Transit Center	Elsa Flores	<i>Paseo Cesar Chavez</i> Ceramic tile benches	1995	Artwork benches are etched (vandalized).	Request additional FY17 resources to do artwork inspection and condition report.
152	Division 9 Facility	Mark Lere	<i>The Metro Machine</i> Terrazzo mural paving	2007	Artwork inspection required.	Request additional FY17 resources to do artwork inspection.