

**Board Report**

File #: 2019-0255, **File Type:** Informational Report

Agenda Number: 27.

**OPERATIONS, SAFETY, AND CUSTOMER EXPERIENCE COMMITTEE
MAY 16, 2019**

SUBJECT: PHASED ART ASSET MANAGEMENT PROGRAM UPDATE

ACTION: RECEIVE AND FILE

RECOMMENDATION

RECEIVE AND FILE Annual Report on the Phased Art Asset Management Program.

ISSUE

At its May 2017 meeting, the Board directed staff to initiate a phased approach to Art Asset Management for existing and new lines. This report provides the requested annual report on these activities.

DISCUSSION

Metro's facility-integrated artworks are unique assets requiring special attention and care to ensure their state of good repair and aesthetic integrity. To address this need, and as directed in the May 2017 Board adopted action, staff has initiated ongoing annual care of the artworks along the oldest lines in the system, the Blue and Red Lines, and is applying lessons learned to new projects. Community members and artists continue to be engaged in the process.

Blue Line

Annual inspections, condition assessments, and regular ongoing care and maintenance of Blue Line artwork are underway. Five artwork repairs have been completed, and three artwork refurbishment projects have been initiated. In addition, artworks are being integrated into the New Blue project and new digital artworks by local artists will be featured on rotating display at each station when the line reopens later this year. All work is being closely coordinated with the New Blue closures and activities.

Red Line

Annual inspections, condition assessments, and regular ongoing care and maintenance of Red Line artwork has also been initiated this year. Efforts have begun to address the line's backlog of deferred artwork maintenance and repairs. Consultants, including artists, conservators, fabricators and other specialized technicians, will assist with this work to ensure these unique assets achieve and retain a state of good repair moving forward.

NEXT STEPS

Staff will continue to pursue the adopted phased art asset management program and will work to ensure the aesthetic integrity of the Blue and Red Line art assets as resourced. Staff will work cross-departmentally to apply lessons learned and to ensure that professional care and management of artworks is included in future operational plans and will continue to provide an annual report as directed by the Board.


ATTACHMENTS

Attachment A - Annual Report on Phased Art Asset Management

Attachment B - Phased Art Asset Management Presentation

Prepared by: Maya Emsden, Deputy Executive Officer (213) 922-2720

Reviewed by: Yvette Rapose, Interim Chief Communications Officer, (213) 418-3154



Phillip A. Washington
Chief Executive Officer

FY19 Metro Public Art Collection: Art Asset Management Report

May 16, 2019

Metro Blue Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
Blue Line Tunnel	<i>Thomas Eatherton</i> <i>Unity</i> LED light sculpture installations	1991	Conduct detailed annual artwork inspection and cleaning. Document conditions.	Not functioning as intended. Electronic artwork requires refurbishment of 82 lightworks.	Funds secured to design develop solution to renovate non-functioning fiber-optic artwork with new, more efficient LED replacements. Work is underway.	Install efficient LED replacement units and vitrine covers restoring artwork as part of New Blue project.
Wardlow	<i>Jacqueline Dreager</i> <i>Great Gathering Place</i> Fiberglass, bronze and steel sculptures; Concrete and steel stools; Glass medallion with imagery	1992	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of gel-coat and wax at fiberglass and bronze elements. Specialized or minor repairs when needed.	Fiberglass artwork sculptural elements reflect deterioration in keeping with UV exposure and age. Bronze and concrete artwork elements are in good condition.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Cleaned and re-coated fiberglass and bronze artwork components, implemented minor repairs to two artwork components.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
7th Street / Metro Center	<i>Joyce Kozloff</i> <i>The Movies: Fantasies and Spectacles</i> Ceramic tile murals	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Low-fire ceramic tile artwork is damaged, reflecting vibration and graffiti etchings.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal grout.
7th Street / Metro Center	<i>Roberto Gil de Montes</i> <i>Heaven to Earth</i> Ceramic tile murals	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile is damaged, one small section is missing.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal grout.
Pico	<i>Robin Brailsford</i> <i>Time and Presence</i> Painted steel canopy panels	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of coatings. Specialized or minor repairs when needed.	Paint at artwork panels has faded.	Performed annual artwork inspections. Working closely with Facilities Maintenance Painters to coordinate re-painting of the artwork canopy panels in FY20 as part of New Blue project.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
San Pedro Street	<i>Sandra Rowe</i> <i>Hope, Dream, Path, Focus, Belief</i> Patinated, etched, pigmented waxed bronze panels; stainless steel kinetic sculptures	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of coatings. Specialized or minor repairs when needed.	Paint at artwork panels has faded. Kinetic elements are damaged.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Clean and re-coat panels, repair kinetic elements as part of New Blue project.
Grand / LATTC	<i>Mark Lere</i> <i>Who, What, Where?</i> Etched and paint filled granite tile paving; etched and paint filled concrete	1994	Completely removed as a result of Metro Blue Line Refurbishment Project. Capital Project underway to replace artwork.	Original artwork completely removed during Metro Blue Line Refurbishment Project.	Design development and engineering revised to incorporate New Blue impacts.	Manage Artist contract to fabricate and install replacement artwork. Scheduled completion FY20.

Metro Blue Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
Vernon	<i>Horace Washington</i> <i>A Tribute to Industry</i> Bronze and powder coated steel stools; galvanized steel benches; stainless steel and painted steel sculpture; ceramic tile	1994	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of sealant. Specialized or minor repairs when needed.	Powder coatings and galvanizing at artwork elements require re-coating.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Powder coated stools will be refurbished offsite in June 2019 as part of New Blue project.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Reinstall powder-coated elements, re-coat galvanized steel benches onsite during New Blue project closures.
103rd Street / Watts Towers	<i>Roberto Salas</i> <i>Blue Line Totems in Red</i> Painted steel columns; ceramic tile	1994	Partially removed as a result of Blue Line refurbishment Project. CP in place with Artist to replace artwork. Conduct detailed annual artwork inspection, documentation and cleaning.	Original artwork partially removed during Metro Blue Line Refurbishment Project.	Engineering and design development completed. Manage Artist contract to fabricate and install replacement artwork. Scheduled completion FY20.	Manage Artist contract to fabricate and install replacement artwork. Scheduled completion FY20. Complete re-painting of station and artwork elements as part of New Blue project.
Pacific Coast Highway	<i>Joe Lewis</i> <i>Twelve Principals</i> Ceramic tile medallions	1994	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Artwork medallions require refurbishments and cleaning.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Refurbishments scheduled for May 2019 as part of New Blue project.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
Anaheim Street	Terry Braunstein <i>Local Odysseys</i> Porcelain enamel medallions	1994	Conduct detailed annual artwork inspection and cleaning. Document conditions. Specialized or minor repairs when needed.	Artwork elements are in good condition.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
Slauson	East Los Streetscapers <i>South Central Suite</i> Porcelain enamel panels; ceramic tile and pigmented concrete and ceramic tile murals	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Porcelain enamel panels require minor repairs. Two porcelain enamel panels are to be refabricated. Ceramic tile artwork is in good condition.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Implemented repairs at ceramic tile, cleaned and sealed grout. Currently working to replace a section of the terra cotta relief and replace attachment system at all porcelain enamel panels before re-installation.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Work with original artist to reproduce two missing porcelain enamel panels.
Compton	Eva Cockcroft <i>Past, Present and Future</i> Ceramic tile panels; ceramic tile columns	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic tile artwork is in good condition.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Implemented significant specialized repairs throughout, cleaned and sealed grout as part of New Blue project.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
5th Street	Jim Isermann <i>Failed Ideals</i> Stain glass medallions	1995	Partially removed as a result of Blue Line refurbishment Project. CP in place with Artist to replace artwork.	Artwork partially removed during Metro Blue Line Refurbishment Project.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Capital budget in place to restore impacted artworks.	Initiate design development and engineering of artwork relocation. Confirm integration of original artwork at new location with Metro Engineering and Construction. Work closely with the original artist throughout scope. Scheduled completion FY20.

Metro Blue Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
1st Street	Paul Tzanetopoulos <i>Breezy and Delightful</i> Porcelain enamel kinetic medallions	1995	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Artwork medallions require cleaning.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Clean medallions panels and replace kinetic elements as part of New Blue project.
Downtown Long Beach	Patrick Mohr <i>Angel Train</i> Anodized aluminum sculptures	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant and wax. Specialized or minor repairs when needed.	Artwork requires cleaning and application of wax sealant.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Clean and apply sealant and wax.
Pacific Ave	June Edmonds <i>We Know Who We Are</i> Glass mosaic medallions	1995	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Artwork medallions require cleaning.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Clean and apply sealant to grout.
Artesia	Lynn Aldrich <i>Blue Line Oasis</i> Stainless steel and ceramic sculpture; glass mosaic tile, painted steel wishing well; glass mosaic panels	1996	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic tile artwork should be monitored for graffiti and further surface loss of low-fire glaze.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Implemented significant repairs at glass mosaic elements, reproduce and install ceramic tile for kiosk, clean and apply sealant to grout as part of New Blue project.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
Washington	Elliot Pinkney <i>Running for the Blue Line</i> Painted steel panels; painted columns	1997	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of coatings. Specialized or minor repairs when needed.	Paint has failed at artwork panels. Painted artwork columns throughout station require repainting.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Repaint artwork columns throughout station in keeping with artist's original design.
Del Amo	Colin Gray <i>Del Amo Wheel</i> Glass fiber reinforced concrete sculpture	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Glass fiber reinforced concrete wheel has been restored in keeping with original conditions.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Implemented significant repairs at glass fiber reinforced concrete sculpture, cleaned and applied sealant and grout as part of New Blue project.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
7th Street / Metro Center	Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Electronic components are outdated and not functioning as intended. Replacement housing has been purchased, requires installation.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Replace lighting housings.

Metro Blue Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
7th Street / Metro Center	K. Kobayashi, N. Korten & M. Perlas <i>Plantings</i> Pigmented concrete benches; cast aluminum, painted steel, gobos and electrical components	2002	Conduct detailed annual artwork inspection and cleaning. Document conditions. Specialized cleaning of gobos and electrical components, replacement of lighting. Biennial application of sealant. Minor repairs when needed.	All projection units are broken. Electrical is outdated and not functioning as intended. Expo Rail Line impacts altered artwork location.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement replacement of electronic components, minor repairs and full cleaning.
Willowbrook / Rosa Parks	<i>Michael Massenburg, Robin Strayhorn</i> <i>Pathways To Freedom</i> Glass mosaic, ceramic tile and concrete benches	2002	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Benches are in good condition. Monitor for future graffiti.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Implemented repairs, cleaned and applied sealant.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
Firestone	Ricardo Mendoza <i>The Will to Progress</i> Ceramic tile mural panels	2004	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Ceramic artwork tile is damaged.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement repairs to tile, clean and seal grout.
Florence	Ricardo Duffy <i>A Florence Moment</i> Ceramic tile murals	2005	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of sealant along grout. Specialized or minor repairs when needed.	Repairs are currently underway at ceramic artwork tile.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Repairs currently underway.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
Willow	Merge Conceptual Design <i>Out of Sight</i> Glass canopy with laminated imagery, GFRC bench	2006	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of sealant. Specialized or minor repairs when needed.	Artwork is in good condition.	Performed annual artwork inspections. Documented artwork and produced detailed condition and corrective action report. Implement minor repairs, clean and seal bench.	Perform annual artwork inspections. Document artwork and update condition and corrective action report.
Willowbrook / Rosa Parks	Judy Baca <i>Metate Bench</i> GFRC benches with ceramic tile	2008	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of sealant. Specialized or minor repairs when needed.	Three benches damaged by contractor during removal (WRP Project).	Documented artwork and produced detailed condition and corrective action report. Obtain estimates for repairs.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement repairs, clean and seal.


Metro Red Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
Union Station	Christopher Sproat <i>Union Chairs</i> Granite benches	1993	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Graffiti damage. Lighting components are not functioning as intended. Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Union Station	Terry Schoonhoven <i>Traveler</i> Ceramic tile mural	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Union Station	Cynthia Carlson <i>LA: City of Angels</i> Hand painted mural with reliefs	1993	Conduct detailed annual artwork inspection and cleaning. Document conditions. Biennial application of gel-coat and wax at fiberglass and bronze elements. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Civic Center / Grand Park	Johnathan Borofsky <i>I Dreamed I Could Fly</i> Hand painted fiberglass sculpture; audio playback system; spotlights	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and software update at audio component. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement. Audio component requires software update.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Pershing Square	Stephen Antonakos <i>Neons for Pershing Square</i> Neon sculptures	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of Neon Transformers. Specialized or minor repairs when needed.	One neon component is broken. Artwork is in need of detailed artwork inspection, neon repairs, transformer replacement and specialized cleaning.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Westlake / MacArthur Park	Francisco Letelier <i>El Sol/La Luna</i> Ceramic tile murals	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Water intrusion at station at walls impacting Artwork mural. Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Westlake / MacArthur Park	Therman Statom <i>Into the Light</i> Glass skylight; acrylic, aluminum, stainless steel and painted steel sculptures; ceramic tile	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.

Metro Red Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
Vermont / Santa Monica	Robert Millar <i>Untitled</i> Text painted on walls throughout; aluminum and polycarbonate panels; colored lighting	1993	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Lighting component (entrance lighting) is outdated and requires complete renovation. Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Union Station: Gateway Transit Center	May Sun and Richard Wyatt	1995	Inspections will result in the development of a Maintenance Plan identifying environmental and deferred maintenance impacts and Action Plan. Resources are needed to conduct detailed artwork inspection and condition report.	Water issues at soffit and pipe. Will require resources to perform artwork inspections and condition report. Based on professional conservator report identifying recommendations, implement specialized cleaning, repairs and conservation.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report. Complete restoration beginning June 2019.	Complete restoration. Perform annual artwork inspections. Document artwork and update condition and corrective action report.
Wilshire / Vermont	Peter Shire <i>Los Angeles Seen</i> Painted steel and stainless steel sculptures	1996	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Kinetic motorized component not working. Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Vermont / Beverly	George Stone <i>Untitled</i> Class fiber reinforced concrete sculptural rock formations	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Vermont / Sunset	Michael Davis <i>Ecliptic/Illume</i> Porcelain, stainless steel, illumination	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Lighting components are not functioning as intended. Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Hollywood / Western	May Sun <i>Untitled</i> Painted aluminum and polycarbonate sculptures; lighting; terrazzo and copper paving murals; etched granite; patinated bronze; ceramic tile throughout	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Lighting components are not functioning as intended. Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Hollywood / Vine	Gilbert "Magu" Lujan <i>Hooray for Hollywood</i> Painted fiberglass and pigmented concrete benches, hand painted ceramic	1999	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	All platform sculptural elements damaged and removed. Ceramic tile artworks located throughout are in need of detailed artwork inspection, specialized cleaning and sealant.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.

Metro Red Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
Hollywood / Highland	Sheila Klein <i>Underground Girl</i> Painted aluminum fixtures, electrical; aluminum and stainless sculpture	2000	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	Electronic components are not functioning as intended. Artwork is in need of detailed artwork inspection, specialized cleaning and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Universal City / Studio City	Margaret Garcia <i>Tree of Califas</i> Carved ceramic tile; stainless steel, painted steel and granite benches; laminated imagery	2000	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Artwork is in need of detailed artwork inspection, specialized cleaning and repairs.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
North Hollywood	Anne Marie Karlsen <i>Kaleidoscope Dreams</i> Ceramic tile	2000	Conduct detailed annual artwork inspection, documentation and cleaning. Biennial replacement of lighting and application of coatings and sealant. Specialized or minor repairs when needed.	Graffiti damage. Artwork is in need of detailed artwork inspection, specialized cleaning and repairs.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
7th Street / Metro Center	Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Electronic components are outdated and not functioning as intended. Replacement housing has been purchased, requires installation.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Install new housings.
Vermont / Beverly	Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Electronic components are outdated and not functioning as intended. Replacement housing has been purchased, requires installation.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Install new housings.
Hollywood / Highland	Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Electronic components are outdated and not functioning as intended. Replacement housing has been purchased, requires installation.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Install new housings.
Wilshire / Normandie	Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Electronic components are outdated and not functioning as intended. Replacement housing has been purchased, requires installation.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Install new housings.
Universal City / Studio City	Rotating Artist <i>Rotating Photo Installations</i> Anodized aluminum, plexiglass, duratrans film	2001	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Electronic components are outdated and not functioning as intended. Replacement housing has been purchased, requires installation.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Install new housings.

Metro Red Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
7th Street / Metro Center	K. Kobayashi, N. Korten & M. Perlas <i>Plantings</i> Pigmented concrete benches; cast aluminum, painted steel, gobos and electrical components	2002	Conduct detailed annual artwork inspection, documentation and cleaning. Annual cleaning and replacement of bulbs at the time of artwork rotation.	Electronic components are outdated and not functioning as intended. Artwork is in need of detailed artwork inspection, specialized cleaning and housing replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Civic Center / Grand Park	Peter Requam <i>Civic Center Benches</i> Granite benches	2004	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Graffiti damage present. Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Civic Center / Grand Park	Samm Kuncze <i>In the Living Rock</i> Glass mosaic and granite murals	2004	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Graffiti damage present. Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Vermont / Santa Monica	George Legrady <i>Kinetic Flow</i> Porcelain enamel mural	2006	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Graffiti damage present. Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Civic Center Station	Faith Ringgold <i>People Portraits: in Creativity, Performing, Sports & Fashion</i> Glass mosaic panels	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Westlake / MacArthur Park	Sonia Romero <i>MacArthur Park, Urban Oasis</i> Hand carved porcelain mosaic panels	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Water intrusion at station at walls impacting Artwork mural. Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Vermont / Beverly	Tyree Guyton <i>People in Motion</i> Glass mosaic mural	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.

Metro Red Line						
Station	Artist / Artwork Title / Components	Year Installed	Annual Maintenance Requirements	Condition	FY19 Progress	FY20 Action Plan
Universal City / Studio City	Stephen Johnson <i>Untitled</i> Glass mosaic mural	2010	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Wilshire / Normandie	Frank Romero <i>Festival of Masks Parade</i> Painted aluminum mural	1996	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Wilshire / Western	Richard Wyatt <i>People Coming People Going</i> Ceramic tile murals	1996	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Wilshire / Western	Pae White <i>The Beppins</i> Pigmented concrete stools; seeded lithocrete paving	2003	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.
Wilshire / Vermont	Bob Zoell <i>No Title</i> Ceramic tile murals	2004	Conduct detailed annual artwork inspection and develop condition report. Document conditions and develop Maintenance Requirements. Specialized or minor repairs when needed.	Broken tile and graffiti etchings throughout. Artwork is in need of detailed artwork inspection, specialized cleaning, sealant and lighting replacement.	Performed first detailed annual artwork inspection and document. Developed a condition and corrective action report.	Perform annual artwork inspections. Document artwork and update condition and corrective action report. Implement minor repairs, clean and seal.



Phased Art Asset Management Annual Report

Operations, Safety, & Customer Experience Committee

May 16, 2019



Lynn Aldrich
Blue Line Oasis
1996

Board Directive

- A. Provide Annual Report
- B. Dedicate resources
- C. Include in future refurbishment projects
- D. Budget as new artworks completed
- E. Create maintenance plan for each artwork
- F. Develop phased approach

Phased Approach

Existing Lines:

- Line by line as each reaches 25 years

New Lines:

- Apply lessons learned
- Include art asset management in start up plans

FY18	FY19	FY21
Blue	Blue	Blue
	Red	Red
		Green
		Crenshaw/LAX

Progress

Blue Line:

- Regular ongoing care underway
- Completed 28 annual inspections and condition assessments
- Completed 5 artwork repairs
- Initiated 3 major artwork refurbishments
- Digital artworks will launch with NewBlue

Red Line:


- Regular ongoing care underway
- Completed 30 annual inspections and condition assessments

Blue Line: Wardlow Station – Artwork Repairs



Jacqueline Dreager
Great Gathering Place
1992

Blue Line: Tunnel Artwork Refurbishment initiated



Thomas Eatherton
Unity
1991

New Blue: Digital Artworks (all stations)

1 **A** Downtown LA 3 min

2 **A** Long Beach 5 min



More People Than You Know Eryn Akili Parker Ross (LP)
Legacy, 2019

M Metro

Maps Arrivals Alerts



Intersection

Red Line: Westlake/MacArthur Park Station – Assessments



Francisco Letelier
El Sol, La Luna
1993



Thank you.